


Ohio Department of Natural Resources Broken Aro Wildlife Area Boundary Survey Jackson County, Ohio



Project Description

Ohio Department of Natural Resources contracted Howerton Engineering & Surveying to perform a boundary survey of the approximately 3,550 acre Broken Aro wildlife area in Jackson County, Ohio.

After extensive deed research and mapping, a base map was generated and overlaid on state aerial photography and Lidar data. Based off the deed mapping, a survey crew explored the Broken Aro property searching for corners, fence and section lines. Once all field recon was complete, the property was located using GPS equipment.

The property corners were then established and all corners and property lines were properly monumented using The State of Ohio Department of Natural Resources Survey Standards. This survey is currently on going and in the final stage of monuments. The field work is anticipated to be completed in January of 2013 and the final plat & legal description will be completed by February of 2013.

Client/Location

Ohio Department of
Natural Resources
Office of Real Estate
2045 Morse Road
Columbus, OH 43229

Client Reference

Bob Sneller
ODNR
(614) 265-6975
Bob.sneller@dnr.state.oh.us

Project Status

Complete

Dates of Service

2013

Special Features

- Boundary Survey
- Deed Mapping
- Deed Research
- GPS
- Aerial Photography
- Lidar Data



**HOWERTON
ENGINEERING &
SURVEYING PLLC**